


Parts of a Milling Cutter



Milling Calculation Formulas

Calculating Cutting Speed

$$v_c = \frac{\pi \times DC \times n}{1,000}$$

$$n = \frac{1,000 \times v_c}{\pi \times DC}$$

v_c : Cutting speed (m/min)

$\pi \approx 3.14$

DC : Cutter diameter (mm)

n : Rotational speed (min⁻¹)

Calculating Feed Rate


$$v_f = f_z \times z \times n$$

$$f_z = \frac{v_f}{z \times n}$$

v_f : Feed rate per minute (mm/min)

f_z : Feed rate per tooth (mm/t)

z : Number of teeth



Power Requirement

$$P_c = \frac{a_e \times a_p \times v_f \times k_c}{60 \times 10^6 \times \eta} = \frac{Q \times k_c}{60 \times 10^3 \times \eta}$$

Horsepower Requirement

$$H = \frac{P_c}{0.75}$$

Chip Removal Amount

$$Q = \frac{a_e \times a_p \times v_f}{1,000}$$

P_c : Power requirement (kw)

H : Required horsepower (HP)

Q : Chip removal amount (cm³/min)

a_e : Cutting width (mm)

v_f : Feed rate (mm/min)

a_p : Depth of cut (mm)

k_c : Specific cutting force (MPa)


Rough value / Steel: 2,500 to 3,000MPa

(Cast iron: 1,500MPa)

(Aluminium: 800MPa)

η : Machine efficiency (about 0.75)


Relation Between Feed Rate, Work Material, Specific Cutting Force



Functions of the Various Cutting Angles

	Description	Symbol	Function	Effect
(1) (2)	Axial rake angle Radial rake angle	A.R. R.R.	Determines chip removal direction, built-up edge, cutting force	Available in positive to negative (large to small) rake angles; Typical combinations: Positive and Negative, Positive and Positive, Negative and Negative
(3)	Approach angle	A.A.	Determines chip thickness, chip removal direction	Large: Thin chips and small cutting force
(4)	True rake angle	T.A.	Effective rake angle	Positive (Large): Excellent machinability Low cutting edge strength. Negative (Small): Strong cutting edge and easy chip adhesion.
(5)	Cutting edge inclination angle	I.A.	Determines chip control direction	Positive (Large): Excellent chip control and small cutting force. Low cutting edge strength.
(6)	Face cutting edge angle	F.A.	Determines surface roughness	Small: Improved surface roughness.
(7)	Relief angle		Determines edge strength, tool life, chattering	


True Rake Angle Chart (T.A)



(Ex.) (1) A.R (Axial rake angle) = +10°
(2) R.R (Radial rake angle) = -30°
(3) A.A (Approach angle) = 60° } → T.A. (True rake angle) = -8° (4)

<Formula> $\tan T.A = \tan R.R \cdot \cos A.A + \tan A.R \cdot \sin A.A$

Inclination Angle (I.A) Chart




(Ex.) (1) A.R (Axial rake angle) = -10°
(2) R.R (Radial rake angle) = +15°
(3) A.A (Approach angle) = 25° } → I (Inclination angle) = -15° (4)

<Formula> $\tan I.R = \tan A.R \cdot \cos A.A - \tan R.R \cdot \sin A.A$


Rake Angle Combination

	Double Positive Type	Negative - Positive Type	Double Negative Type
Edge Combination and Chip Removal (A.R: Axial rake angle R.R: Radial rake angle A.A: Approach angle ↻ : Chip and removal direction ↻ : Rotation)			
Advantages	Good cutting action	Excellent chip removal and cutting action	Double-sided inserts can be used and higher cutting edge strength
Disadvantages	Lower cutting edge strength and only single-sided inserts can be used	Only single-sided inserts can be used	Dull cutting action
Application	For general milling of steel and low rigidity work piece	For Steel, Cast iron, Stainless steel, Alloy steel	For light milling of cast iron and steel
Series	DPG Type	WGX Type, UFO Type	DGC Type, DNX Type
Chips (Ex.) (Work material: SCM435 v _c =130m/min f _z =0.23mm/t a _p =3mm)			

Relation Between Engagement Angle and Tool Life



● Relation between the number of simultaneously engaged cutting edges and cutting force: Normally, cutting width is considered to be appropriate with 70 to 80% of the cutter diameter engaged as shown in example d). However, this may not apply due to the actual rigidity of the machine or work piece, and machine horsepower.



To Improve Surface Roughness


(1) Inserts with wiper flat

When all the cutting edges have wiper flats, a few teeth are intentionally elevated to play the role of a wiper insert.





- Insert equipped with straight wiper flat (Face angle: 15° - 1°)
- Insert equipped with curved wiper flat (Curvature ≈ R500 (example))

(2) Wiper insert assembling system

A system to protrude one or two inserts (wiper inserts) with a smooth curved edge just a little beyond the other teeth to wipe the milled surface. (Applies to WGC, RF types, etc.)



■ Tool Failure and Remedies

Failure		Basic Remedies		Remedy Examples											
Cutting Edge Failure	<p>Excessive Flank Wear</p> 	<p>Tool Material</p> <ul style="list-style-type: none"> · Select a more wear resistant grade. <p>Carbide (P30 → P20) → { Coated K20 → K10 } → Cermet</p> <p>Cutting Conditions</p> <ul style="list-style-type: none"> · Reduce cutting speeds. Increase feed rate. 	<ul style="list-style-type: none"> · Recommended insert grades <table border="1"> <thead> <tr> <th></th> <th>Steel</th> <th>Cast Iron</th> <th>Non-Ferrous Alloy</th> </tr> </thead> <tbody> <tr> <td>Finishing</td> <td>T250A, T4500A (Cermet)</td> <td>ACK100 (Coated Carbide) BN7000 (SUMIBORON)</td> <td>DA1000 (SUMIDIA)</td> </tr> <tr> <td>Roughing</td> <td>ACP100 (Coated Carbide)</td> <td>ACK200 (Coated Carbide)</td> <td>DL1000 (Coated Carbide)</td> </tr> </tbody> </table>		Steel	Cast Iron	Non-Ferrous Alloy	Finishing	T250A, T4500A (Cermet)	ACK100 (Coated Carbide) BN7000 (SUMIBORON)	DA1000 (SUMIDIA)	Roughing	ACP100 (Coated Carbide)	ACK200 (Coated Carbide)	DL1000 (Coated Carbide)
		Steel	Cast Iron	Non-Ferrous Alloy											
	Finishing	T250A, T4500A (Cermet)	ACK100 (Coated Carbide) BN7000 (SUMIBORON)	DA1000 (SUMIDIA)											
	Roughing	ACP100 (Coated Carbide)	ACK200 (Coated Carbide)	DL1000 (Coated Carbide)											
<p>Excessive Crater Wear</p> 	<p>Tool Material</p> <ul style="list-style-type: none"> · Select a crater-resistant grade. <p>Cutting Conditions</p> <ul style="list-style-type: none"> · Reduce cutting speeds. Reduce depth-of-cut and feed rate. 	<ul style="list-style-type: none"> · Recommended insert grades <table border="1"> <thead> <tr> <th></th> <th>Steel</th> <th>Cast Iron</th> <th>Non-Ferrous Alloy</th> </tr> </thead> <tbody> <tr> <td>Finishing</td> <td>T250A, T4500A (Cermet)</td> <td>ACK100 (Coated Carbide)</td> <td>DA1000 (SUMIDIA)</td> </tr> <tr> <td>Roughing</td> <td>ACP100 (Coated Carbide)</td> <td>ACK200 (Coated Carbide)</td> <td>DL1000 (Coated Carbide)</td> </tr> </tbody> </table>		Steel	Cast Iron	Non-Ferrous Alloy	Finishing	T250A, T4500A (Cermet)	ACK100 (Coated Carbide)	DA1000 (SUMIDIA)	Roughing	ACP100 (Coated Carbide)	ACK200 (Coated Carbide)	DL1000 (Coated Carbide)	
	Steel	Cast Iron	Non-Ferrous Alloy												
Finishing	T250A, T4500A (Cermet)	ACK100 (Coated Carbide)	DA1000 (SUMIDIA)												
Roughing	ACP100 (Coated Carbide)	ACK200 (Coated Carbide)	DL1000 (Coated Carbide)												
<p>Chipping</p> 	<p>Tool Material</p> <ul style="list-style-type: none"> · Change to tougher grades. P10 → P20 → P30 K01 → K10 → K20 <p>Tool Design</p> <ul style="list-style-type: none"> · Select a negative-positive cutter configuration with a large peripheral cutting edge angle (small approach angle). · Reinforce the cutting edge (Honing). · Select a strong edge insert (G → H). <p>Cutting Conditions</p> <ul style="list-style-type: none"> · Reduce feed rates. 	<ul style="list-style-type: none"> · Recommended insert grades <table border="1"> <thead> <tr> <th></th> <th>Steel</th> <th>Cast Iron</th> </tr> </thead> <tbody> <tr> <td>Finishing</td> <td>ACP200 (Coated Carbide)</td> <td>ACK200 (Coated Carbide)</td> </tr> <tr> <td>Roughing</td> <td>ACP300 (Coated Carbide)</td> <td>ACK300 (Coated Carbide)</td> </tr> </tbody> </table> <ul style="list-style-type: none"> · Recommended cutter: SEC-WaveMill WGX Type · Cutting conditions: Refer to H20 		Steel	Cast Iron	Finishing	ACP200 (Coated Carbide)	ACK200 (Coated Carbide)	Roughing	ACP300 (Coated Carbide)	ACK300 (Coated Carbide)				
	Steel	Cast Iron													
Finishing	ACP200 (Coated Carbide)	ACK200 (Coated Carbide)													
Roughing	ACP300 (Coated Carbide)	ACK300 (Coated Carbide)													
<p>Breakage</p> 	<p>Tool Material</p> <ul style="list-style-type: none"> · If it is due to excessive low speeds or very low feed rates, select an adhesion resistant grade. · If it is due to thermal cracking, select a thermal impact resistant grade. <p>Tool Design</p> <ul style="list-style-type: none"> · Select a negative-positive (or negative) cutter configuration with a large peripheral cutting edge angle (small approach angle). · Reinforce the cutting edge (Honing). · Select a stronger chipbreaker (G → H) · Increase insert size (Thickness in particular). <p>Cutting Conditions</p> <ul style="list-style-type: none"> · Select appropriate conditions with regards to the particular application. 	<ul style="list-style-type: none"> · Recommended insert grades <table border="1"> <thead> <tr> <th></th> <th>Steel</th> <th>Cast Iron</th> </tr> </thead> <tbody> <tr> <td>Roughing</td> <td>ACP300 (Coated Carbide)</td> <td>ACK300 (Coated Carbide)</td> </tr> </tbody> </table> <ul style="list-style-type: none"> · Recommended cutter: SEC-WaveMill WGX Type · Insert thickness: 3.18 → 4.76mm · Insert type: Standard → Strong edge type · Cutting conditions: Refer to H20 		Steel	Cast Iron	Roughing	ACP300 (Coated Carbide)	ACK300 (Coated Carbide)							
	Steel	Cast Iron													
Roughing	ACP300 (Coated Carbide)	ACK300 (Coated Carbide)													
Others	<p>Unsatisfactory Machined Surface Finish</p>	<p>Tool Material</p> <ul style="list-style-type: none"> · Select an adhesion resistant grade. <p>Carbide → Cermet</p> <p>Tool Design</p> <ul style="list-style-type: none"> · Improve axial runout of cutting edges. (Use a cutter with less runout) (Attach correct inserts.) · Use wiper inserts. <p>Cutting Conditions</p> <ul style="list-style-type: none"> · Use special purpose cutters designed for finishing. · Increase cutting speeds 	<ul style="list-style-type: none"> · Recommended insert grades <table border="1"> <thead> <tr> <th></th> <th>Steel</th> <th>Cast Iron</th> <th>Non-Ferrous Alloy</th> </tr> </thead> <tbody> <tr> <td>General Purpose Cutter Insert</td> <td>WGX type* ACP200 (Coated Carbide)</td> <td>DGC type ACK200 (Coated Carbide)</td> <td>RF type* H1 (Carbide) DL1000 (Coated Carbide)</td> </tr> <tr> <td>Finishing Cutter Insert</td> <td>WGX type T4500A (Cermet)</td> <td>FMU type BN7000 (SUMIBORON)</td> <td>RF type DA1000 (SUMIDIA)</td> </tr> </tbody> </table> <p>* marked cutters can be fitted with wiper inserts.</p>		Steel	Cast Iron	Non-Ferrous Alloy	General Purpose Cutter Insert	WGX type* ACP200 (Coated Carbide)	DGC type ACK200 (Coated Carbide)	RF type* H1 (Carbide) DL1000 (Coated Carbide)	Finishing Cutter Insert	WGX type T4500A (Cermet)	FMU type BN7000 (SUMIBORON)	RF type DA1000 (SUMIDIA)
		Steel	Cast Iron	Non-Ferrous Alloy											
	General Purpose Cutter Insert	WGX type* ACP200 (Coated Carbide)	DGC type ACK200 (Coated Carbide)	RF type* H1 (Carbide) DL1000 (Coated Carbide)											
	Finishing Cutter Insert	WGX type T4500A (Cermet)	FMU type BN7000 (SUMIBORON)	RF type DA1000 (SUMIDIA)											
	<p>Chattering</p>	<p>Tool Design</p> <ul style="list-style-type: none"> · Select a cutter with sharp cutting edges. · Use an irregular pitched cutter. <p>Cutting Conditions</p> <ul style="list-style-type: none"> · Reduce feed rates. <p>Others</p> <ul style="list-style-type: none"> · Improve workpiece and cutter clamp rigidity. 	<ul style="list-style-type: none"> · Recommended cutter <p>For Steel: SEC-WaveMill WGX Type</p> <p>For Cast Iron: SEC-Sumi Dual Mill DGC Type</p> <p>For Non-Ferrous Alloy: High Speed cutter for Aluminium RF type</p>												
<p>Unsatisfactory Chip Control</p>	<p>Tool Design</p> <ul style="list-style-type: none"> · Select cutter with good chip removal features. · Reduce number of teeth. · Enlarge chip pocket. 	<ul style="list-style-type: none"> · Recommended cutter: SEC-WaveMill WGX Type 													
<p>Edge Chipping On Workpiece</p>	<p>Tool Design</p> <ul style="list-style-type: none"> · Increase the peripheral cutting edge angle (decrease the approach angle). · Select a stronger chipbreaker (G → L). <p>Cutting Conditions</p> <ul style="list-style-type: none"> · Reduce feed rates. 	<ul style="list-style-type: none"> · Recommended cutter: SEC-WaveMill WGX Type 													
<p>Burr On Workpiece</p>	<p>Tool Design</p> <ul style="list-style-type: none"> · Select a cutter with sharp cutting edges. · Increase feed rates. <p>Cutting Conditions</p> <ul style="list-style-type: none"> · Select an insert designed for low burr. 	<ul style="list-style-type: none"> · Recommended cutter: SEC-WaveMill WGX Type + FG Breaker DGC Type + FG Breaker 													