



Parts of a Drill




● Point Angle and Force




When point angle is large, thrust becomes large but torque becomes small.

● Point Angle and Burr




When point angle is large, burr height becomes low.


● Minimum Requirement Relief Angle




● Web Thickness and Thrust




● Decrease Chisel Width by Thinning



● Relation Between Edge Treatment and Cutting Force



Reference of Power Requirement and Thrust



Cutting Condition Selection

Control Cutting Force for Low Rigid Machine

The following table shows the relation between edge treatment width and cutting force. If a problem caused by cutting force occurs, reduce either the feed rate or the edge treatment width.


Cutting Conditions		Edge Treatment Width			
		0.15mm		0.05mm	
v_c (m/min)	f (mm/rev)	Torque (N·m)	Thrust (N)	Torque (N·m)	Thrust (N)
40	0.38	12.8	2,820	12.0	2,520
50	0.30	10.8	2,520	9.4	1,920
60	0.25	9.2	2,320	7.6	1,640
60	0.15	6.4	1,640	5.2	1,100

Drill : ø10mm
Work : S50C 230HB

High Speed Machining Recommendation

If there is surplus capacity with enough machine power and sufficient rigidity, adopting higher efficiency conditions would improve the tool life; however, sufficient amount of coolant must be supplied.

Wear Example



$v_c=60$ m/min

$v_c=120$ m/min

Work : S50C (230HB)


Cond.: $f = 0.3$ mm/rev

H = 50mm

Life : 600holes (Cutting length: 30m)


Explanation of Margins (Difference between single and double margins)

Single Margin (2 guides: circled parts)



● Shape used on most drills


Double Margin (4 guides: circled parts)




● 4-point guiding reduces hole bending and undulation for improved stability and accuracy during deep hole drilling.

Run-out Accuracy

For the run-out accuracy of web-thinned drills, not only the difference in lip height (B) but also the run-out after thinning (A) is important.




(A): The run-out accuracy of thinning point
(B): The difference of the lip height



Peripheral Run-out Accuracy when Tool Rotates

● When the tool rotates
The peripheral run-out accuracy of the drill mounted on the spindle should be controlled within 0.03mm. If the run-out exceeds the limit, the drilled hole will also become large causing an increase in the horizontal cutting force, which may result in drill breakage.



Run-out: within 0.03mm

Peripheral Run-out (mm)	Hole Expansion		Cutting Force*	
	0	0.05(mm)	0	10 (kg)
0.005	~0.01	~0.02	~0.5	~1.5
0.09	~0.05	~0.15	~5.0	~15.0


* Horizontal cutting force.

Drill: MDS120MK Work material: S50C (230HB)

Cutting Conditions: $v_c=50\text{m/min}$, $f=0.3\text{mm/rev}$, $H=38\text{mm}$

Water soluble coolant


● When the work material rotates
Not only the peripheral run-out at the drill edge (A) but also the concentricity at (B) should be controlled within 0.03mm.



Run-out: within 0.03mm


Influence of Work Material Surface

● Work material with slanted or uneven surface
If the surface of the hole entrance or exit is slanted or uneven, decrease the feed rate to 1/3 to 1/2 of the recommended cutting condition.




How to Use a Long Drill

● Problem
When using a long drill (XHGS type), DAK type drill, SMDH-D type drill, or SMDH-12.5D type drill at high rotation speeds, the run-out of the drill tip may cause a deviation of the entry point as shown on the right, bending the drill hole and resulting in drill breakage.



● Remedies

Method 1




Method 2 * Low rotational speed minimises centrifugal forces and prevents drill bending.




Drill Maintenance

(1) Collet Selection and Maintenance

- Ensure proper chucking of drills to prevent vibration. Collet chucks (thrust bearing type) provide strong and secure grip force.
(Drill chucks and keyless chucks are not suitable for MultiDrills as they have a weaker grip force.)




- When replacing drills, regularly remove cutting debris inside the collet by cleaning the collet and the spindle with oil. Repair marks with an oilstone.



(2) Drill Installation

- The peripheral run-out of the drill mounted on the spindle should be controlled within 0.03mm.
- Do not chuck on the drill flute.
(If drill flute inside the holder, chip removal will be obstructed thus causing damage to the drills.)




Calculation of Power Consumption and Thrust

Calculating Cutting Speed

$$v_c = \frac{\pi \times DC \times n}{1,000}$$

$$n = \frac{1,000 \times v_c}{\pi \times DC}$$



- Calculating Feed Rate Per Revolution and Per Tooth
 $v_f = n \times f$ $f = \frac{v_f}{n}$
 π : Circular Constant ≈ 3.14
 DC: Drill Diameter (mm)
 n : Spindle Speeds (min^{-1})
 v_f : Feed Rate (mm/min)
 f : Feed Rate per Revolution (mm/rev)
- Calculation of Cutting Time
 $T = \frac{H}{v_f}$
 H : Drilling Depth (mm)
 T : Cutting Time (min)
 HB : Brinell Hardness

● Calculation of Power Consumption and Thrust

$$\text{Power Consumption (kW)} = HB \times DC^{0.68} \times v_c^{1.27} \times f^{0.59} / 36,000$$


$$\text{Thrust (N)} = 0.24 \times HB \times DC^{0.95} \times f^{0.61} \times 9.8$$

* When designing the machine, an allowance of 1.6 x Power Consumption and 1.4 x Thrust should be given.

Using Cutting Oil


(1) Choosing of Cutting Oil

- If cutting speed is more than 40m/min, cutting oil JISW1 type 2 is recommended for its good cooling effect & chip removal ability as it is highly soluble.
- If cutting speed is below 40m/min and longer tool life is a priority, non-water cutting oil JISA1 type 2, an activated sulphuric chloride oil, is recommended for its lubricity.
* Non-water soluble oil may be flammable. To prevent fire, a substantial amount of oil should be used to cool the component so that smoke or heat will not be generated.




(2) Supply of Coolant

- If using an external supply of coolant, fill a substantial amount from the inlet. Oil pressure range: 0.3 to 0.5 MPa, oil level range: 3 to 10 l/min.
- If using an internal supply of coolant (Ex: HK Type) for holes $\phi 4$ or smaller, the oil pressure must be at least 1.5MPa to ensure a sufficient supply of coolant.
holes $\phi 6$ or larger: 0.5 to 1.0 MPa for hole depths below 3 times the drill diameter, and 1 to 2 MPa or more for hole depths more than 3 times the diameter.




Work Clamping

High thrust forces occur during high-efficiency drilling. Therefore, the workpiece must be supported to prevent fracture caused by bending. Also, large torques and horizontal cutting forces occur. Therefore, the workpiece must be clamped firmly enough to withstand them.



Drill Regrinding

- When to regrind
When one or two feed marks (lines) appear on the margin, when corner wear reaches the margin width, or when small chipping occurs, it indicates that the drill needs to be sent for regrinding.
- How and where to regrind
We recommend applying regrinding and recoating. Recoating is recommended to prevent shortening of tool life. Note, ask us or an approved vendor to recoat with our proprietary coating.
- Regrinding on your own
Customers regrinding their own drills can obtain MultiDrill Regrinding Instructions from us directly or your vendor.



■ Troubleshooting for Drilling

	Failure	Cause	Basic Remedies	Remedy Examples	
Drill Failure	Excessive Wear on Cutting Edge	· Inappropriate cutting conditions.	· Use higher cutting speeds. · Increase feed rates.	· Refer to the upper limit of the recommended conditions listed in the Igetalloy Cutting Tools Catalogue. · Refer to the upper limit of the recommended conditions listed in the Igetalloy Cutting Tools Catalogue.	
		· Unsuitable cutting fluid.	· Reduce pressure if using internal coolant. · Use cutting fluid with more lubricity.	· 1.5 MPa or below (external coolant if hole depth is L/D = 2 or less). · Use JIS A1 grade No. 1 or its equivalent.	
	Chisel Point Chipping	· Off-center starts.	· Reduce feed rate at entry point. · Pre-processing to ensure flat contact surface.	· $f=0.08$ to 0.12mm/rev · Use endmill to produce flat surface.	
		· Equipment and/or work material lacks rigidity.	· Change cutting conditions to reduce resistance. · Improve work material clamp rigidity.	· Increase v_c and decrease f (reduce thrust).	
		· Cutting edge is too weak.	· Increase size of chisel width. · Increase amount of honing on cutting edge.	· Set chisel width from 0.1 to 0.2 mm. · Make thinning section of central area 1.5x current width.	
	Chipping On Peripheral Cutting Edge	· Inappropriate drilling conditions.	· Decrease the cutting speed. · Reduce feed rate.	· Refer to the lower limit of recommended conditions listed in the Igetalloy Cutting Tools Catalogue. · Refer to the lower limit of recommended conditions listed in the Igetalloy Cutting Tools Catalogue.	
		· Unsuitable cutting fluid.	· Use cutting fluid with more lubricity.	· Use JIS A1 grade No. 1 or its equivalent.	
		· Equipment and/or work material lacks rigidity.	· Improve work material clamp rigidity.		
		· Cutting edge is too weak.	· Increase amount of honing on cutting edge. · Reduce the amount of front flank angle.	· Make peripheral cutting edge 1.5x current width. · Reduce the amount of front flank angle by 2° to 3° .	
		· Peripheral cutting edge starts cutting first.	· Increase margin width (W margin).	· Increase margin width by 2 to 3x current width.	
		· Cutting interrupted when drilling through workpiece.	· Reduce feed rate. · Increase amount of honing on cutting edge. · Reduce the amount of front flank angle.	· Refer to the lower limit of recommended conditions listed in the Igetalloy Cutting Tools Catalogue. · Make peripheral cutting edge 1.5x current width. · Reduce the amount of front flank angle by 2° to 3° .	
	Margin Wear	· Inappropriate drilling conditions.	· Decrease the cutting speed.	· Refer to the lower limit of recommended conditions listed in the Igetalloy Cutting Tools Catalogue.	
		· Unsuitable cutting fluid.	· Use cutting fluid with more lubricity. · Increase coolant supply.	· Use JIS A1 grade No. 1 or its equivalent. · If using external coolant, change to internal coolant supply.	
		· Latent margin wear.	· Early regrind to ensure adequate back taper.	· Regrind margin damage to 1 mm or less.	
		· Unsuitable tool design.	· Increase amount of back taper. · Reduce margin width.	· Make back taper 0.5/100. · Decrease margin width to two-thirds of current width.	
	Drill Breakage	· Chip build-up.	· Use optimal cutting conditions and tools. · Increase coolant supply.	· Refer to the table of recommended conditions in the Igetalloy Cutting Tools Catalogue. · If using external coolant, change to internal coolant supply.	
		· Collet clamp lacks strength.	· Use collet with strong grip force.	· Replace collet chuck if damaged. · Use collet holder one size bigger.	
		· Equipment and/or work material lacks rigidity.	· Improve work material clamp rigidity.		
Unsatisfactory Hole Accuracy	Oversized Holes	· Reduce feed rate at entry point.	· $f=0.08$ to 0.12mm/rev		
		· Off-center starts.	· Decrease the cutting speed. · Pre-processing to ensure flat contact surface.	· Refer to the lower limit of recommended conditions listed in the Igetalloy Cutting Tools Catalogue. · Use endmill to produce flat surface.	
		· Drill bit lacks rigidity.	· Use optimal drill type for hole depth. · Improve overall rigidity of drill.	· Refer to the Igetalloy Cutting Tools Catalogue. · Large web with comparatively small flute.	
		· Drill bit has run-out	· Improve drill clamp precision. · Improve drill clamp rigidity.	· Replace collet chuck if damaged. · Use collet holder one size bigger.	
		· Equipment and/or work material lacks rigidity.	· Improve work material clamp rigidity.		
	Poor Surface Finish	· Inappropriate cutting conditions.	· Increase cutting speeds. · Reduce feed rate.	· Refer to the upper limit of the recommended conditions listed in the Igetalloy Cutting Tools Catalogue. · Refer to the lower limit of recommended conditions listed in the Igetalloy Cutting Tools Catalogue.	
		· Unsuitable cutting fluid.	· Use cutting fluid with more lubricity.	· Use JIS A1 grade No. 1 or its equivalent.	
	Holes Are Not Straight	· Off-center starts.	· Increase feed rates.	· Refer to the upper limit of the recommended conditions listed in the Igetalloy Cutting Tools Catalogue.	
		· Drill is not mounted properly.	· Improve drill clamp precision. · Improve drill clamp rigidity.	· Replace collet chuck if damaged. · Use collet holder one size bigger.	
		· Equipment and/or work material lacks rigidity.	· Improve work material clamp rigidity. · Select a double margin tool.		
	Unsatisfactory Chip Control	Packing Of Chips	· Inappropriate drilling conditions.	· Increase cutting speeds. · Increase feed rates.	· Refer to the upper limit of the recommended conditions listed in the Igetalloy Cutting Tools Catalogue. · Refer to the upper limit of the recommended conditions listed in the Igetalloy Cutting Tools Catalogue.
			· Poor chip evacuation.	· Increase the amount or pressure of coolant applied if using internal coolant.	
Long Stringy Chips		· Inappropriate drilling conditions.	· Increase feed rates. · Increase cutting speeds.	· Refer to the upper limit of the recommended conditions listed in the Igetalloy Cutting Tools Catalogue. · Refer to the upper limit of the recommended conditions listed in the Igetalloy Cutting Tools Catalogue.	
		· Cooling effect is too strong.	· Reduce pressure if using internal coolant.	· Keep pressure 1.5 MPa or lower if using internal coolant.	
	· Dull cutting edge.	· Reduce amount of edge honing.	· Reduce to around two-thirds of current width.		